

Graphically, Figure 2 provides a summary by township of the structural housing conditions determined by this survey. The number situated at the top of each symbol indicates the total number of housing units located within each township, and the bar graph and corresponding percentages indicate the composition of standard, deteriorated and delapidated housing found within each township. Generally, Figure 2 indicates that the highest percentage of substandard housing (deteriorated and delapidated units) exists in the rural townships. The percentage is in conjunction with the total number of homes within a particular township. In ranking order, the sequence of substandard housing by townships are as follows:

1. 34.7 - Watkins
2. 32.1 - Townsville
3. 25.1 - Kittrell
4. 22.0 - Middleburg/Nutbush
5. 19.0 - Williamsboro
6. 18.7 - Henderson
7. 18.7 - Sandy Creek
8. 12.1 - Dabney

The following section of this chapter will utilize the data obtained from the Structural Quality Survey in combination with census data to provide a more detailed picture of Vance County's existing housing stock.